



## 2021 NEW ITEMS JUNE

**RELEASING:**

HEATER CORES COVERING OVER 110,000 VIO

Pro Source Heater Cores™ are engineered and tested to provide years of trouble-free operation. Backed by over 50 years of mobile HVAC experience, Pro Source heater cores are designed to match O.E. fit, form and function. When a repair is needed, choose a quality aftermarket heater core.

Fix it once and fix it right with Pro Source Heater Cores™.



**P/N 92406**

VIO 53,082

(05-03) Suzuki Grand Vitara

(06-03) XL-7



**P/N 92399**

VIO 38,920

(12-05) Acura RL



**P/N 92400**

VIO 18,923

(17-14) Chevrolet Caprice

(17-14) SS

### Don't forget to test for Electrolysis!

Aluminum heater cores fail due to:

- Erosion from high flow rate
- Contaminated coolant
- Poor quality coolant

Electrolysis is a process of chemical changes in the cooling system where ions exchange between the heater core and engine coolant. This results in a breakdown of the heater core material, leaving a pinhole size leak at or within the heater core. This is usually caused by not properly maintaining the cooling system.